

## Möllers Group – Special Retrofit Solutions

Retrofit offer for all stretch-hooders (HSA)  
installed up until 2010



We understand packaging.

**möllers**  
group

## Retrofit offer for all stretch-hooders (HSA) installed up until 2010

If the defect of a wear-part can lead to downtime of the HSA, it is recommended to take a preventative retrofit measure which is an equally efficient as well as plannable alternative. On all Möllers stretch-hooders installed up until 2010 screw jacks were employed on their stretch-arms. These are costly wear-parts with long replacement times which have since been optimally replaced by rack modules.

Functionality and availability are significantly improved. Thus, the screw jack is no longer installed on new HSA systems and is also now obsolete for spare parts. In any individual required case, time-consuming and costly replication would be required.



### Our recommendation: rack drives instead of screw jack

As part of a retrofit offensive we recommend fully replacing the screw jacks of the stretch unit with rack drives in order to be able to produce securely in a state-of-the-art manner.



### Task: greater availability of the HSA

The goal of the service team is to eliminate production loss due to machine downtime. Short delivery times and availability of parts from stock are the key to success here, this is achieved through the use of the current rack modules.



### Our retrofit offer for maximum reliability

As part of a retrofit, the Möllers Group service team will equip the stretch units with rack drive including motor and inverter.

These components are always available from stock and provide optimal system availability. A complete replacement or replacement parts can be supplied at short notice. Thanks to reduced procurement costs and longer lifetime this also results in measurable savings potential.




### Optimum cost control – concrete savings potential

The Möllers service team will gladly make you an offer in this regard which is tailored to your plant.

We are looking forward to your inquiry!

### » Planned modernization for smoothly functioning plants



» Stretch-arm with rack drive

### Your contact person



Michael Jungilligens

Fon +49 2521 88-444  
spares@moellers.com

### Publisher

Maschinenfabrik Möllers GmbH  
Sudhoferweg 93-97  
59269 Beckum

Fon +49 2521 88-0  
Fax +49 2521 88-100

info@moellersgroup.com  
www.moellersgroup.com



Inferior Court:  
Münster  
HRB7676  
VAT-ID.No.:  
DE 218694419  
CEO: Jörg Freyer